


● Title: **Track Sensor and Timer Cable Pinouts**

● Date: **01/29/09**


Discussion: Typical cable pinouts for RaceAmerica timers.

RJ11 Sensor Cable Connector
(viewed contacts facing up/tab down)



Pin 1 - Proprietary input or n/c
Pin 2 - Ground
Pin 3 - Sensor output
Pin 4 - Sensor output or n/c
Pin 5 - 12VDC
Pin 6 - Proprietary input or n/c

RJ45 Timer Input Cable Connector
(viewed contacts facing up/tab down)



Pin 1 - Proprietary input or n/c
Pin 2 - Ground
Pin 3 - Sensor Input
Pin 4 - Sensor Input or n/c
Pin 5 - Sensor Input or n/c
Pin 6 - Sensor Input or n/c
Pin 7 - 12VDC
Pin 8 - Proprietary input or n/c